MATERIAL SAFETY DATA SHEET

· · · · · · · · · · · · · · · · · · ·	FOR COATINGS, RES				MY			
DATE OF PREP. August 1977	(Approved by U.S. Department of	of Labor "Easentla	lly Similar" to Forr	n OSHA-20) /				
Section I								
MANUFACTURER'S NAME Koppers	Company, Inc.							
STREET ADDRESS 5431 Di	strict Blvd. CITY	STATE, AND ZIP	code Vern	on, CA 9004	0			
EMERGENCY TELEPHONE NO. 213	- 726-8666							
PRODUCT CLASS Acid Co	MANU	MANUFACTURERS CODE IDENTIFICATION						
TRADE NAME		C-152-66						
	Section II — HAZ	ARDOUS	INGREDIE	NTS		•		
INGREDIENT		PERCENT	T PPM	mg/M ^a	LEL	VAPOR PRESSURE		
Anhydrol 190 (ethyl alcohol) Phosphoric Acid		65.79 15.3	. 1000 -	1880 1	4.3	40mm/19°C .03mm/20°C		
		•						
					,			
	Section III -	- PHYSIC	AL DATA					
BOILING RANGE 170-212°F		VAPOR DE		HEAVIER _	LIGHTE	R. THAN AIR		
EVAPORATION RATE FASTER					7.75 <u>+</u> .2			
	Section IV — FIRE AN	D EXPLOS	ION HAZ	ARD DATA				
DOT CATEGORY Flammab	FLASH PÓ	INT 53°F TC	3		LEL 4.3			
EXTINGUISHING MEDIA		.`			•			
Carbon	dioxide, foam or dry	chemical						
		•						
unusual fire and explosion hazaron May form explosion	s n explosive vapor mix ve limits . Do not u	ture betweense welding	een upper a g or cutti	and lower	•			

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water.

or near drum (even empty).

Section V — HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE N/A EFFECTS OF OVEREXPOSURE	
Headache, nausea, moderately irriting to eyes and skin.	
EMERGENCY AND FIRST AID PROCEDURES	
Remove victims from vapors - restore breathing if necessary. Remove from skin with soap and water.	
Flush eyes with water.	,
Section VI — REACTIVITY DATA	
STABILITY UNSTABLE STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid)	
HAZARDOUS DECOMPOSITION PRODUCTS CO, CO ₂ , aldehydes, and other organics, phosphorous oxide.	
HAZARDOUS POLYMERIZATION MAY OCCUR X WILL NOT OCCUR CONDITIONS TO AVOID	
Section VII — SPILL OR LEAK PROCEDURES	
steps to be taken in case material is released or spilled Remove sources of ignition. Apply sawdust or other absorbent material - keep material from spreading.	
WASTE DISPOSAL METHOD Put in metal container and seal for disposal.	
Section VIII — SPECIAL PROTECTION INFORMATION	_
RESPIRATORY PROTECTION For confined areas use Bureau of Mines Respiratory Device Approval 25 B-13	
BM2304 Face Piece BM2304 Cartridge	
BM2313 Filter	
BM2313 Filter Clipd VENTILATION Ventilation should be adequate to keep lower level below LEL	
veneriation should be adequate to keep lower level below had	
PROTECTIVE GLOVES Rubber	
OTHER PROTECTION Safety OTHER PROTECTIVE EQUIPMENT Rubber soles must be worn (no static electricity)	
Section IX — SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Flammable - store away from open flame and high heat	
OTHER PRECAUTIONS Do not take internally - avoid prolonged contact with skin	